

Kashf inspection center (KASHF)

Generated on 12 June, 2025 • Report #445

Chevrolet Corvette Z06 , 2016

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom
97450666211



CONFIDENCE SCORE
90/100

Vehicle Information

Date	Fahsy Report
12 June, 2025	445
Organization Name	Car Make
KASHF	Chevrolet
Car Owner Name	Car Model
السيد أبو كنان المحترم	Chevrolet Corvette Z06
Buyer Name	Vehicle Color
السيد أبو كنان المحترم	أصفر
Year Of Manufacturing	Engine Type
2016	fuel
Engine Capacity	Current Mileage
6000	188506
VIN NO.	Plate Number
D71G5114915	867204




Car Options
Screen


Final Score

✓ Final Decision
Approved


👥 Market Value
N/A



Excellent



Overall Rating



Kashf inspection center (KASHF)

Generated on 12 June, 2025 • Report #445

Chevrolet Corvette Z06 , 2016

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE
90/100

Service & Maintenance History

Condition Chart	System Inspection	Very Good	Good	Bad
	Chassis Condition	60	40	0

Kashf inspection center (KASHF)

Generated on 12 June, 2025 • Report #445

Chevrolet Corvette Z06 , 2016

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE
90/100

Remarks



Good



Very Good



Bad

Kashf inspection center (KASHF)

Generated on 12 June, 2025 • Report #445

Chevrolet Corvette Z06 , 2016

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

90/100

**Chassis Condition**

Chassis and frame are inspected for sedan

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding join marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding join marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

**Front Left Chassis Dimensions**

Very Good

**Front Right Chassis Dimensions**

Very Good

**Rear Left Chassis Dimensions**

Very Good

**Rear Right Chassis Dimensions**

Very Good

**Undercarriage condition**

- ضرب حصي

Good

**Front Frame**

- ضربة أمامية

Good

**Rear Frame**

- ضربة خلفية

Good

**Right Side Frame**

Good

Kashf inspection center (KASHF)

Generated on 12 June, 2025 • Report #445

Chevrolet Corvette Z06 , 2016

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

90/100

i Left Side Frame

Very Good

i Upper Frame

Very Good

Kashf inspection center (KASHF)

Generated on 12 June, 2025 • Report #445

Chevrolet Corvette Z06 , 2016

Building No 356 - Street, 340 Salwa Rd, Doha, Qatar - Speed Marine Salwa Main Showroom

97450666211



CONFIDENCE SCORE

90/100



All Notes

All Notes

- ضرب حصى
- ضربة أمامية
- ضربة خلفية